






























HAZARDOUS MATERIAL LABEL TEST CHART

30 RANDOM 100 MM (4 IN) LABELS

This bar should be 150mm long.

	A	B	C	D	E	F
H						
1	1A 	1B 	1C 	1D 	1E 	1F 
2	2A 	2B 	2C 	2D 	2E 	2F 
3	3A 	3B 	3C 	3D 	3E 	3F 
4	4A 	4B 	4C 	4D 	4E 	4F 
5	5A 	5B 	5C 	5D 	5E 	5F 